








MAIN CLOCK




ISP UART




BOOT JUMPER








PHY CLOCK



ETHERNET SOCKET



If you put 10 ohm resistor instead of FR1,FR2 there is some improvement in the problem.



Cannot open file C:\Users\Public\Documents\Altium\AD14\Templates\Emko-logo.bmp	
PROJE KODU:	DOSYA ADI:
PROJE ADI:	Microcontroller_2.SchDoc
BÖLÜM ADI: MICROCONTROLLER	TARİH: 26.01.2018
ÇİZEN:	ONAY:
REV. NO:	
SAYFA: 2 /	